

Notes on Sec. 10, T20S R4W WM

At  $\frac{1}{4}$  Corner between Sections 10 & 15, I found the

- 30" Fir N 20°E down and in bad shape
- 6" Fir S 82°W is all gone

White Fir 16 S 66 $\frac{1}{2}$ °W marked by County Survey, has been reduced to a stump and in bad condition.

There is a 4" Yew pole put in the ground as a flag as it is in place I marked it  $\frac{1}{4}$  S, from which bears

- Incense Cedar 26" brs. North 60°E 59 ft. marked  $\frac{1}{4}$  S 15 H S BT
- Red Cedar 26" brs. North 51°W 126 ft. marked  $\frac{1}{4}$  S 10 H S BT

I run North across Sec. 10 closing 121 ft. West of  $\frac{1}{4}$  cor. I corrected the course and run South to center line between east and west  $\frac{1}{4}$  corners of Sec. 10 at the hub of S 10 being this cross line I set a Cedar stake 4x6 3' high for a monument

- Marked M no. 1 H S from which
- A Fir 16" brs. S 1°West 16 ft.
- A Fir 17" " N 34 $\frac{1}{2}$ °W 6.4 ft.

April 6, 1951.

Present: George Overholser, Donald Overholser, Curtis Morgan

Preliminary lines were Var. 22°

The center line running from East to West closes 14 ft. N of the East  $\frac{1}{4}$  cor. . . .

JESSE J. HOOKER

Field Notes on  $\frac{1}{4}$  Sec. Cor. between Secs. 19 & 20, T20S R5W WM

May 28, 1951, I found this corner in bad shape because of some eager axeman has chopped in past the face destroying all but a small portion of the figures of the only tree that could still be read.

I set in place for this corner a Fir stake marked  $\frac{1}{4}$  S, from which

The original Fir now 48 in. brs. N 7°W 16 lks. instead of S 7°W as noted. Some marks remain.

Original Fir now 54 in. S 83°E 51 lks. is all burned out at face.

New bearing trees:

Hemlock 19 in. diam. Brs. S 37 $\frac{1}{2}$ °W 6 $\frac{1}{4}$  ft.

Fir 8 in. diam. Brs. N 12°E 17 $\frac{1}{2}$  ft.

Var. 21 $\frac{1}{2}$ °

Present: Elmer Ladd  
Charles Beeman  
Will H. Smith

JESSE J. HOOKER

CS. 53/1-79