

REV. T 275 R's 344 W  $\frac{1}{4}$  S | S  
12 | 7

FD. IRON PIPE WITH BRASS CAP -  
PULLED OUT OF GROUND BY UPROOTED  
TREE.

FD. FIR STUMP S 37° W 56  $\frac{1}{2}$  FT.  
PARTIAL SCRIBING VISIBLE (1917 B.T.)

FD. FIR N 31° E 45  $\frac{1}{2}$  FT. - TREE  
UPROOTED & DOWN - SCARS BURIED IN  
MUD. (1917 B.T.)

FD. 9" FIR S 55  $\frac{1}{4}$ ° E 9  $\frac{1}{2}$  FT. - TREE  
UPROOTED & DOWN. - SCRIBING VISIBLE.  
(1958 B.T.)

FD. 11" FIR S 25  $\frac{1}{2}$ ° W 50  $\frac{1}{2}$  FT. - TREE  
UPROOTED & DOWN. - SCRIBING VISIBLE.  
(1958 B.T.)

RESET BRASS CAP IN ORIGINAL  
POSITION.

BLAZE & SCRIBE 2 NEW TREES:

16" DOUG. FIR S 87° E 34  $\frac{1}{2}$  FT.  
MKD. "  $\frac{1}{4}$  S 7 CS BT "

10" DOUG. FIR N 7° W 38  $\frac{1}{2}$  FT.  
MKD. "  $\frac{1}{4}$  S 12 CS BT "

(BRASS CAP SET ORIGINALLY  
IN CADASTRAL RESURVEY OF 1958)

JAN. 2, 1963

M.G.

V.T.

M.S.

*W. E. Jeffrey*

+\* O ✓

Section 17 Twp E7S Rge 4 W Date: 12/13/68


How was corner identified? Bearing trees &

brass cap

Condition of corner: Brass cap pulled out of ground. It is in a rootwad.

Best route to reach corner: County road to Clover Hill Ranch. Take ranch road leading uphill.

Other Remarks:



Quadrant	NE	NW	SE	SW
Species & Size	DF 2"		DF 8"	DF 1 1/2" Stump
Dist. & Bearing	531°W 67K		N55°W 141K	N37°E 861K
Condition of Scribble				
Original or Resurvey	Resurvey		Resurvey	Original
Appearance of B.S.	Blowdown		Blowdown	Stump
Tags, Marks, etc.	Tag		Tag	Tag

Signed