

Review $\frac{1}{4}$ S 47 53 T275 R5W

Fd. O.B.T.s 25 follows -

ORIG. 8" Now 16" oak S, 81 $\frac{1}{2}$ W. 60 $\frac{1}{2}$ ft.

Down - only 2 xe MKs Fd - Badly Ripped.

No trace of orig. S.E. B.T. - we find

Boyers 1944 B.T. (see Rev. # 47)

2 12" Now 16" Fir N, 80 $^{\circ}$ E. 13 $\frac{1}{2}$ ft.

Record. 139 $\frac{1}{2}$ ft. - alive - previously opened

& shows " $\frac{1}{4}$ 53 CS" scribe - Ring count

26 years - Ridge top to south would

fit call distance of 95 LKs, good from

This location - if we use Boyers

Record dist., Ridge would be approx 4 chains

S. - 2 $\frac{1}{2}$ COR. point set 1" I.P. & Brass

cap MKd. "COUNTY SUPERVISORS OFFICE

1970 T275 $\frac{1}{4}$ 54/53 R5W" Note

Brass cap lies 2 $^{\circ}$ ft. East of N-S fence.

MARK. New B.T.s -

9" D. Fir S, 38 $^{\circ}$ E. 19 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 53 CS BT"

18" B. oak S, 19 $^{\circ}$ W. 54 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 54 CS BT"

Boyers 16" D. Fir N, 80 $^{\circ}$ E. 13 $\frac{1}{2}$ ft.

We Rescribe " $\frac{1}{4}$ 53 CS BT"

Feb. 11, 1970

V.R.T.

#136 R.T. Tracy C.S. No. 53/30 N.D.E.

#136 130