

Renew Sec. COR. of $\frac{57}{518} | \frac{58}{517}$ T275 R5W

Ed. $\frac{3}{4}$ " x 16" IRON BAR in place

as called for in Ren. #55 & O.B.T.s

as follows -

Ren. #55 BT - 22" now 26" B.O. N, 23° W, 102 $\frac{1}{2}$ ft,

2 live - previously opened - faint scribe mks

on Decayed Blaze - good Lower SCAR -

orig. 11" now 20" W, 02K N, 64 $\frac{1}{2}$ ° E, 40 $\frac{1}{2}$ ft,

2 live - previously opened - nearly Rehealed

orig. 16" now 24" Y, 02K N, 13 $\frac{1}{2}$ ° W, 102 $\frac{3}{4}$ ft,

now only Burned stump 6" high.

orig. 18" now 34" W, 02K S 53° E, 62° ft.

2 live - previously opened - Blazes Decayed

orig. 14" now 22" W, 02K S, 40 $\frac{1}{2}$ ° W, 88 $\frac{1}{2}$ ft,

2 live - previously opened - Blaze Rehealed,

also find Cedar Post scribed "CS SEC COR",

at cor. point in place of I. BAR - set

1" I.P. & BRASS cap MKd. "COUNTY

SURVEYORS OFFICE 1970

T275 $\frac{57}{518} | \frac{58}{517}$ R5W" Reset old cor.

material along side BRASS cap

MARK New B.T.s -

15" W, 02K N, 44° E, 50 $\frac{1}{2}$ ft,

Mkd. "T275 R5W S 8 CS BT"

#137

(See over)

C. & M. 53/38 ³⁴ #137

20" Forked B. OAK S. 41° E, 34 $\frac{8}{16}$ FT.

Mkd. "T275 R5W S17 CS BT"

12" W. OAK S. 37° W, 36 $\frac{1}{16}$ FT.

Mkd. "T275 R5W S18 CS BT"

26" B. OAK N. 23° W, 102 $\frac{4}{16}$ FT.

Rescribe "T275 R5W S7 CS BT"

This cor. lies on steep Easterly
slope approx 125 ft. East of Ridge
Top sloping southerly.

Feb. 13, 1970

W.R.T.
J.G.H.
V.D.B.

W.R.T. Tracy

N.F. 29-5 $\frac{1}{4}$, $\frac{7}{18}$ W. Do not find any
O.B.T.s or B.T.s recorded in Ren. #
Due to water tank & housing.

Fd. O.K. $\frac{1}{4}$ S18/S17 25-7

2" I.P. in place - 4 B.T.s called for
in Ren. # 45 -

Bearing to S.W. B.T. is S. 84° W.

Not S. 76° W. - All Distances O.K.