

Renew N  $\frac{1}{16}$  of 528 | 527 T255 R4W

Fd. at Cor. 1 BT only as follows-

10" Now 12" D. FIR S.  $68^{\circ}$  W 19' ft.

Recorded ~~as~~ a W. F.R. Partially grown  
over scrub we open & find "N  $\frac{1}{16}$  528"

GLO Brass Cap & other BT Destroyed  
By slide in small creek. The BT

fd. does not appear to have affected

by slide. Because of the possibility

of continued sliding in the immediate  
area of the cor., we set a witness cor.

32' ft south as follows - a 1" I.P.

& Brass Cap MKD "COUNTY SURVEYORS

OFFICE 1965 T255 R4W

W.C. 32 FT. N. to N.  $\frac{1}{16}$  528 | 527 "

& MKD. new BTs -

24" Cedar S.  $56^{\circ}$  E 20' ft.

MKD. " W.C. N  $\frac{1}{16}$  527 CS BT "

6" D. FIR S.  $87^{\circ}$  W 25' ft.

MKD. " W.C. N  $\frac{1}{16}$  528 CS BT "

JAN. 15, 1965

URT.  
M.D.  
J.B.

~~A/R Tracy~~

TOP  
110

C.S. File No.

53/47-12