

Renew Sec. Cor.  $\frac{529}{532} | \frac{528}{533}$  T255 R4W

Fd. BLM. Brass Cap MKd. " T255

R4W  $\frac{529}{532} | \frac{528}{533}$  1957" & Two Live

BTs -

25" Now 25" cedar S.  $57\frac{1}{2}^\circ$  E. 108 $\frac{3}{4}$  ft.

Shows "T255 R4W 533 BT" on partially  
healed blaze.

7" Now 10" Fir N.  $64\frac{1}{4}^\circ$  W. 141 $\frac{3}{4}$  ft.

face pitched over we cannot disturb.  
Other BTs turned out & out of place.

MARK New BTs -

9" D. Fir N.  $40^\circ$  E. 6 $\frac{1}{2}$  ft.

Mkd. " T255 R4W 528 CS BT "

8" D. Fir S.  $71^\circ$  W. 29 $\frac{1}{2}$  ft.

Mkd. " T255 R4W 532 CS BT "

This cor lies on very steep  
South slope 25 $\frac{1}{2}$  ft south of  
E.-W. Fence.

Feb. 26, 1965 FILED V.R.T.

RECEIVED M.P.  
J.B.

FEB 26 1965

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

~~OV~~  
~~TK~~  
#115

C. S. File No.

53/47-13