

Renewal

21/22

T325 RSW

Found:

3/4" I Rod at 1/4 cor

Also Reference Measurements as follows

Hub and Tack S21 1/2 W 16 1/2 ft
Sight on 3 trunk pole

Sight on 16" W. oak, S35 E 26
feet.

Hub & tack on this line However not
found.

Also said cor falls at correct sta.
of 194450

cor falls in state Highway R/W

Preceding information taken from
their notes.

DIETZEN NO. 388-6

Renewal

New Bearing Tree

8" W oak

scribed

K522 c.s. BT

S49 1/2 E

85 E

Center Pole No. E 2908 S20 W

PS Nail in Base of Pole

41 E

Note: cor lies north of R/W
Fence 32 ft

9-7-67
JWB
JWB
JWB

179

#170

D.W. J.W.B.


C.S. File No. 53/52-58

OREGON STATE HIGHWAY DEPARTMENT

TRANSIT SHEET

Form E33-30M-7-63-52193

sight on 3 trunk Ash
at edge of small creek



1/4 Corn
21
22

Sta 194 + 50

T 325 R 5
KW WM

sight on 16" oak

Occ 20.30 E set in Transit

Genyerville

C. S. File No. 53/52-58