

Renew

S33 S34

T30S R9W

Found:

BT $\frac{1}{4}$ cor. N" cedar now 15"

$\frac{1}{4}$ S scribed on west side

15" Douglas Fir now 27" N86 $\frac{1}{2}$ W 24 1/2 S

12" Fir SSE 16 $\frac{1}{2}$ 1/2 S
No trace of this tree.

Renewed.

Set Brass cap BT corner MRD,

County Surveyors office 1965

T30S R9W

$\frac{1}{4}$ S33 S34

Brass cap is set very close to
16 cedar tree on the west side.

New Bearing Trees:

27" Douglas Fir N86 $\frac{1}{2}$ W 15"

Scribed $\frac{1}{4}$ S33 CS BT

22" Douglas Fir N80E 38"

Scribed $\frac{1}{4}$ S34 CS BT

This corner is about 66 Ft. on the
North side of Ridge Top.

Oct 20, 1965

[Handwritten signature]

#93
+ ~~10~~

DIETZGEN NO. 385-6