

Renewal

56
57

T305 39W

Found,

Brass cap of cor. 450

U.S. Dept of Interior,

T305 39W

56

57

1902

22" Douglas Fir S 42 1/2 E 8 1/4 HS

56 BT

13" Douglas Fir N 35 W 42 1/4 HS

57 BT

This tree rotten in trunk and cracked.

Also in area of a lot of blow down

Original BT.

5" Fir

S 16 E

7 1/2

Tree opened no scribe visible

12" Fir

N 61 E

3 1/4 HS

Did not find this tree.

Renewal

New BT.

20" Douglas Fir N 44 E 16 1/2

scribed 56 CS BT

OCT 27, 1965

J. M. G.

J. C. B.

F. W. J.

V 475
+ X

C.S. File No. 53/53-11

DIETZGEN NO. 385-6