

Renewal

522

327

T29S R9W

Found:

Bronze cap M.M.P.

County Surveyors office

T29S R9W

522

Re. 63

527

1959

26" Fir stump S79E 85° (orig)

20" Fir stump N22W 90°

16" R. Fir now 17" N22W 91°

Shows two good faces

New Bearing Trees:

17" Fir S10W 33°

Scribed $\frac{1}{2}$ 527 CS BT.

This cor is on top of ridge
just before descending going west
possible to visit to cor on old road
from NW Sec. cor of (20)

12-7-65

J.M.C.

J.C. 63

F.W.J.

DIETZGEN NO. 385-6

X#78

C.S. File No. 53/53-71

Section

B7

Top

29

Page

9

Date:

15 Sept

How was corner identified?


Corner Cap - Douglas County

Condition of corner:

No DT's - Two strings

Best route to reach corner:

all the left



Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Open, Marks, etc.				

Other Remarks:

Hayward

Signed

CS 53/53-7