

Renew Sec. Cor. 531/532 T205 R10W

Fd. 1951 GLD. BRASS cap properly MKd
 out of ground & 1951 B.T.S as follows -
 12" Now 15" cedar S. 49° W. 7 7/8 ft

2 live - Scribe visible on nearly healed Blaze

N.W. B.T. has slid downhill - Now STUMP.

S.E. B.T. Now STUMP in proper position

N.E. B.T. Turned out. - We Reset

BRASS cap at cor. point & MK New
 B.T.S -

10" D. FIR NORTH 53 1/2 ft.

Mkd. " T205 R10W 529 CS BT "

10" maple S. 67° E. 28 1/8 ft.

Mkd. " T205 R10W 532 CS BT "

No Tree available in sec. 30 - This
 cor. lies on very steep southerly
 slope.

April 4, 1968

U.R.T.
 F.J.
 V.P.

A. R. Tracy

484
 W. K. J. No. 13.

C. S. File No. 53/66 24