

Review Sec. Cor. 55 T205 R9W

Fd. 1921 G.L.O. BRASS cap in place

& firmly set, & Q.B.T. as follows-

20" Now 26" FIR N. 83°W, 22 1/2 ft.

Now sawed stump - shows scar. No

Trace other B.T. Due to slide.

There being no trees close - we

set 5/8" I.R. in front of B.T. stump

on N. 83°W. Bearing, 20 1/2 ft. &

set 5/8" I.R., North 10° ft.

Set 6 ft. steel fence post

along side BRASS cap. This

cor. lies on very steep

Northealy slope approx.

200 ft. from Log. Landing in

sec. 5.

July 19, 1968

V.R.T.  
J.H.  
V.R.

G.R. Tracy

#4-719-9  
#9-20-9

JT W. B.

C.S. File No. 53/66-69