

Renew Sec. Cors 517/516 T205 R10w

Fd 1951 G.L.O. BRASS cap properly
Mkd - out of Ground - & B.T.s 25 follows

38" Now 40" FIR N. 35 3/4° E. 33 3/4 ft.

2 live - healed Blaze.

18" Now 18" FIR S. 25° E. 10 6/8 ft.

2 live - Badly injured on Blaze side.

16" Now 18" FIR S. 20° W. 8 6/8 ft.

2 live - healed Blaze

22" FIR N. 32° W. 20 8/8 ft.

Now Stump - scribes visible on
unhealed Blaze - Reset BRASS cap

at cor. point & MK. New B.T.

9" D. FIR S. 63° E. 20 4/8 ft.

Mkd. T205 R10w 516 CS BT "

No TREES available in Sec. 8

This cor. Lies on steep southerly
slope approx. 60 ft. S. of

Ridge Top - cutoff in Sec. 8

April 5, 1968

VRT.
F.J.

A. R. Tray

#20, J. W. B.

C. S. File No. 53/66-85