

RENEW SEC. COR. ^{55/54}~~58/59~~ T205 R11W

Fd. Cedar post in place & BTs as follows (see Rev # 10)

22" Now 24" D. Fir N. 4° E. 74 5 ft.

2 live - Record Bearing N. 6° E. - scribe MKs visible on nearly healed blaze.

21" Now 23" Alder S. 60 1/2° W. 31 5 ft.

2 live - scribe visible on healing blaze.

14" Now 17" cedar S. 28° E. 42 5 ft.

2 live - Record Bearing S. 32° E. - nearly healed blaze - N.W. Alder B.T. gone -

Orig. 36" cedar B.T. to N.W. still

in evidence - at cor. point set

1" I.P. & Brass cap MKd. COUNTY

SURVEYORS OFFICE 1970 T205

^{55/54}~~58/59~~ R11W " Reset cedar post

along side - No suitable trees

to N.W. for new B.T. - cor. lies

on steep N.E. slope 66 ft. N.

of top of spur sloping E. & 40 ft.

south of canyon course East.

Feb 24, 1970

V.R.T.
T.A.H.
V.D.P.

V.R. Tracy

#86

D.K.
D.W.P.

C.S. File No. 53/66-92