

Renew $\frac{1}{4}$ 526/525 T205 RAW

Fd 1954 cad. BRASS cap out of place
as determined from B.T. as follows

ORIG Now 62" FIR N. 83° E. 29 $\frac{1}{2}$ ft.

Sawed stump - Burned NO SCRIBE visible.

ORIG. Now 50" FIR N. 51° W. 13 $\frac{1}{2}$ ft.

Sawed stump - 1954 Rescribe visible.

1954 8" Hemlock S. 76° E. 7 $\frac{3}{4}$ ft.

Now shattered stump - SCRIBE visible.

S.W. Hemlock down & out of Place.

We Reset BRASS cap ~~at~~ cor point

& set Steel fence post along side.

MK. New B.T. -

12" cedar N. 79° W. 98 $\frac{1}{2}$ ft.

Mkd. $\frac{1}{4}$ 526 CS BT "

No Trees close to East,

This cor. Lies 30 ft. East
of Coldwater Creek access Rd.

May 15, 1969

V.R.T.
J.G.H.
V.D.P.

V.R.T. Ray

MK.
T.W.B.

W/12

G.S. File No. ~~53/66-106~~