

REN. T 23 S R 9 W (W.C.)  $\frac{1}{4}$  S 1 S 27 26

FD. DOUG. FIR (NOW 29" DIAM.)

S 6° E 73 1/2 FD. - PREVIOUSLY OPENED. -  
GOOD SCRIBING VISIBLE "  $\frac{1}{4}$  S 26 BT "

N.W. B.T. NOT FD.

CORNER POSITION FALLS ON  
BARE ROCK FACE - VERY STEEP  
SLOPE. - IMPOSSIBLE TO SET CORNER  
HERE. - SET WITNESS CORNER SOUTH

75 FT. OF  $\frac{1}{4}$  COR. - DROVE  $\frac{3}{4}$ "

ROD AT WIT. COR.

BLAZE & SCRIBE:

27" DOUG. FIR N 41° W 11 1/2 FT.

MKD. "WC  $\frac{1}{4}$  S 27 CS BT"

THE B.T. FOR THE  $\frac{1}{4}$  COR.

29" DOUG. FIR BEARS N 85° E 7 1/8 FT.

FROM WITNESS COR.

OCT. 19, 1964

*Milo E. Godfrey*

M.G.  
W.S.  
M.S.

7-A  
+ \*

C. S. File No. 53/84-2

3

Section ~~835~~ 835 Rge 9 Date: 6-29-64

26

HOW WAS CORNER IDENTIFIED? Tree on corner

Tree at rt angles

Condition of corner: questionable 1 BT

RENEWED  
OCT. 19, 1964  
Hub Co. Coffey

Best route to reach corner: Soap Creek jeep road  
200' left of jeep road.

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.	CS	53/84-2		

Karl B. Remond  
Signed  
GLM Core Day