

Renew Sec. Cor.  $\frac{5}{8} \frac{4}{9}$

T22-5W.

Found:

6" Oak (now 8") N4W 102.6 ft.

Shows good scar.

11" Fir (now 13") N26E 49.8 ft.

Shows good scar

24" R. Fir S8W 26.3 ft.  
(Down)

24" R. Fir (Broken) S40E 84 ft.

Shows remnants of  
scribing

Corner lands on sandstone  
as described in Ren #66

but brass cap is missing.

Set  $3\frac{1}{4}$ " I. Rod at Corner  
(Cor. is approx. 30" N. of F.C. Cor.)

New Bearing Trees:

18" D. Fir S31E 55.0

Marked T225 R5W59  
C.S. BT

18" D. Fir S39W 103.0

Marked T225 R5W58  
C.S. BT.

March 10, 1965

B.R. M.S. File No. 53/101-34

DIETZGEN NO. 385-6

+ ~~112~~