

Renew Sec Cor. $\frac{10}{15} \frac{11}{14}$

T225 R4W

Found:

A $\frac{3}{4}$ " Aluminum pipe
at Corner. Weyerhaeuser
set this from original
bearing trees.

Set brass cap in place
of pipe which was bent.

County Surveyors OFF.

T225 R4W $\frac{10}{15} \frac{11}{14}$ 1965

New Bearing Trees:

8" Fir N58E 96.3

Marked -225 4W S11 CS BT

12" inc. Cedar N71W 62.7

Marked

T225 R4W S10 CS. B.T.

12" Fir S39W 38.0

Marked

T225 R4W S15 CS BT

48" Fir S48E 44.6

T225 R4W S14 CS BT

Jan 19, 1965

ER.

N.S. File No. 53/10474

+ X^W
#108 (over)

We found every thing
as described by Weyer -
hauser except the
N.E. Tree is now a burnt
stump and shows no
scribing. This stump is
good for bearing & dist.

FILED
RECEIVED

JAN 25 1964

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

FILED
RECEIVED

JAN 19 1964

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.