


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

MEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 22S RANGE 4W
 SECTION 34 CORNER C N 1/16
 COUNTY Douglas OREGON

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
6" W. Oak	North	82.2	-	X	X	-
8" " "	877°W	59.4	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Grass
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) _____ %

Field

FROM CORNER -

NORTH: 4 20% 70' Fence Field

SOUTH: Level 150' Fence "

EAST: Level "

WEST: Level for 50' then 4 25% "
50' Fence.

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: William R. Hill DATE: Jan. 6, 1961
~~LAND AGENT~~

ASSISTED BY: Robert Barta

COPIES SENT TO: _____

UNDER THE SUPERVISION OF:

GLO SURVEY RECORD			PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
CORNER	DATE: _____		
ACCESSORIES:			
BEARING-	LINKS-	FEET-	
SURVEY RECORD			PRESENT CONDITION: _____
DATE: _____			

CORNER SET: Found hole where 2" I. Pipe had been MAG. DECL.: _____
removed by farmer, Drove 1 1/2" x 18" Oak hub flush with top of ground.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/105-28