

Renew Sec. Cor. 528/527 T215 R10W
Fd. COR. Stone - Broken in half
with 3 chiseled notches on East
edge. Stone in place & O.B.T. as follows
14" now 28" Fir S. 64° W. 205 ft,
alive - shows good scar - we do not type.

Rescribe "T215 R10W 528 CS BT"

Alder to SE. gone - hole where
it would have been fits bearing
& distance. at COR. point, set
1" I.P. & Brass cap MKd. "COUNTY
SURVEYOR'S OFFICE 1968

T215 528/527 R10W" & Deposit
COR. STONES at base of BRASSCAP
MARK new B.T. -

14" D. Fir S. 3° E. 162 ft.
MKd. "T215 R10W 527 CS BT"

This COR. Lies on VERY steep
N.W. slope approx 75 ft. west
of STA. 33+79 on U.S.F.S. "L" Line
for Road, not yet constructed.

July 8, 1968

U. R. T.
J. H.
U. P.

J. R. Tracy

*26 O.K. J. W. C. C.S. No. 54/1-4