

Renew W.  $\frac{1}{4}$  S30 T21S R10W  
Fd. 1919 G.L.O. BRASS CAP BROKEN  
off concrete filled I.P. in place  
& O.B.T.S as follows -  
16" Now 30" FIR N,  $44^{\circ}$  E, 21  $\frac{1}{2}$  ft.  
2 live - shows good SCAR - wed do not open  
& Rescribe - " $\frac{1}{4}$  S30 CS BT"  
14" Now 24" FIR S,  $38^{\circ}$  E, 29  $\frac{1}{2}$  ft.  
2 live - shows good SCAR - wed do not open  
& Rescribe " $\frac{1}{4}$  S30 CS BT"  
2<sup>nd</sup> COR. point in place of old I.P.  
set 1" I.P. & BRASS CAP MKD. "COUNTY  
SURVEYOR'S OFFICE 1968  
T21S R11W  $\frac{1}{4}$  S30 R10W" - NO  
New TREES MKD., None close. This  
COR. LIES APPROX 132 ft. S. OF  
SMALL CREEK COURSE S.E. ON  
VERY STEEP N.E. Slope. The  
E.  $\frac{1}{4}$  OF SEC 25 BEAR SOUTH 47  $\frac{3}{4}$  ft.  
RECORD 49  $\frac{5}{8}$  ft.

July 18, 1968

J/R Tray

V.R.T.  
J.H.  
U.P.

\*24

#53-T21-11

O.W.

J.W.B.

C.S. File No.

52/1-6