

Review $\frac{1}{4}$ 536 T215 R10W
T225

FD. 1919 G.L.O. BRASS cap Laying on
ground - Pipe Broke 10" below surface
& o.B.T.s as follows -

8" Now 9" FIR N, 24° E. 25 $\frac{1}{2}$ ft.

Now S N 29 - "36" scribe visible on
opened blaze - Badly decayed.

6" Now 24" ^{FIR} N. 55° W (Record N. 65° W) 13 $\frac{3}{4}$ ft.

2 live - shows fair scar - we do not
open - we Rescribe " $\frac{1}{4}$ 536 CS BT"

at cor point in place of old pipe
set 1" I.P. & BRASS cap MKd. "COUNTY
SURVEYOR'S OFFICE 1968"

T215 $\frac{1}{4}$ 536 T225 R10W & Deposit

old cor. material along side BRASS - MK. New B.T.s -

28" D. FIR N, 25° E. 45 $\frac{3}{4}$ ft.

Mkd. " $\frac{1}{4}$ 536 CS BT"

This cor. lies on moderate
southerly slope in timber &
brush, approx. 348 ft. S. 88° W of
North $\frac{1}{4}$ Sec 1 of T225 R10W.

June 10, 1968

V.R.F.
J.H.
VP.

#41
#21-21-10
③

O.K. J.V.V.
C.S. File No. 54/1-8