

Renew S,  $\frac{1}{4}$  533 T215 R10W

Fd. concrete filled I.P. at cor. Paint  
Broken off & BRASS cap on ground  
along side. O.B.T.s as follows -

5" Now 10" FIR N. 23° E. 185 ft.

2 live - good scar - we Rescribe

" $\frac{1}{4}$  533 CS BT" (above old scar)

8" Now 14" FIR N. 76° W. 153 ft.

2 live - good scar - we Rescribe -

" $\frac{1}{4}$  533 CS BT" (above old scar)

at cor. point in place of old pipe  
set 1" I.P. & BRASS cap MKd. "COUNTY  
SURVEYORS OFFICE 1968

T215  $\frac{1}{4}$  533 R10W T225 "

This cor. lies 25 ft. west of  
Rock Spur sloping 5.40° W. on  
steep westerly slope. Deposit  
old cor. material along side BRASS cap.

July 9, 1968

U.R.T.  
J.H.  
W.P.

*V.R. Tray*

#48-T22-10

O.K. J.W.B.

#29

C.S. No. 541-17