

Renew Sec. Cor. <sup>52 51</sup> 511/512 T215 R10W

Fd. 1919 G.L.O. BRASS cap with pipe  
BROKEN off at ground level 17" Down  
FROM Top. & 1919 B.T.S as follows -

16" Now 18" Alder N. 44° E. 8<sup>6</sup> ft.

almost Dead, Face Rotted away - no scribe

12" Now 14" Alder S. 52° E. 8<sup>6</sup> ft.

Now 20 ft high snag - fragmentary scribe  
MKs. on unhealed blaze.

12" Now 15" Alder S. 32° W. 13<sup>9</sup> ft.

Nearly dead - unhealed blaze face Rotted.

No scribe - No Trace NW. BT. - Set 1" I.P.

& BRASS cap MKd. "COUNTY SURVEYOR'S  
OFFICE 1967 T215 <sup>52 51</sup> 511/512 R10W" in place  
of old I.P. & MK. New B.T.s -

10" Hemlock N. 13° E. 15<sup>1</sup> ft.

Mkd. "T215 R10W S1CS BT"

14" Hemlock S. 79° E. 25<sup>6</sup> ft.

Mkd. "T215 R10W S12CS BT"

8" Hemlock S. 10° W. 36<sup>7</sup> ft.

Mkd. "T215 R10W S11CS BT"

15" Hemlock N. 84° W. 25<sup>2</sup> ft.

Mkd. "T215 R10W S2CS BT"

This cor. Lies approx. 150 West of  
Rd. # 2171. Reset old Brass along side.

March 15, 1967 *V.R. Gray*

V.R. Gray

J.H.

D.W.

C.S. No. 37