

Renew Sec. Cor. ^{R9W 518} 519 T235 R8W

Fd. B.T.'s as follows -

orig. 50" Now 72" Fir N. 15° E. 18⁵ ft.

2 live - shows good SCOR - do not open

orig. 20" Now 38" Cedar S. 75° E. 44³ ft.

2 live - scribe visible on unhealed B/T 2E.

orig. 14" Now 30" cedar N. 79° W. 9² ft.

Badly injured. No scribe fd. No trace

of sand stone called Cor. Set 1" I.P.

BRASS cap MKd. COUNTY SURVEYOR'S

OFFICE, 1967 T235 R8W ⁵¹⁸ 519 R8W"

& MK. New B.T.s -

8" Hemlock S. 59° E. 26³ ft.

Mkd. "T235 R8W 519 CS BT"

14" Hemlock N. 75° E. 30⁸ ft.

Mkd. "T235 R8W 518 CS BT"

This cor. lies steep S.W. slope

approx. 200 ft. N. of creek

course N.W.

Jan. 31, 1967

FILED

V.R.T.

RECEIVED

J.H.

D.W.

[Handwritten signature]

JAN 31 1967

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#11
#25- T235 R8W

J.W.B.

C.S. File No. 54/1256