

Renew Sec. Cor. $\frac{531}{56} \frac{332}{55}$ T215 T223 R4W

Fd. 1962 CS BRSS cap properly mkd
& firmly set. (See Ren. #51) & BTs
as follows -

14" Now 15" W. FIR N. 32° E. 18 $\frac{1}{2}$ ft.

2 live - nearly healed Blaze - Scribe vis.

18" Now 19" D. FIR N. 50° W. 15 $\frac{3}{4}$ ft.

2 live - nearly healed Blaze

13" Now 14" D. FIR S. 17° W. 58 $\frac{1}{4}$ ft.

2 live - Blaze healed.

S.E. B.T. Down - we mk. new B.T. -

13" R. FIR S. 71° E. 91 $\frac{1}{4}$ ft.

Mkd. " T225 R4W 55 CS BT "

probable orig B.T. STUMP still
in place. This cor. lies
N. 65° E. 4 $\frac{5}{8}$ ft. FROM fence cor.
Fences E. - W. & S.

Dec. 27, 1968

U.A.T.
F.L.M.
V.P.

G/R + Ray

T21-4
T22-4

O.K.
J.W.M.

C.S. File No. 54/14-91