

Renew $\frac{1}{4}$ 527 | 526 T235 R4W

Fd. Haines "T" IRON $\frac{3}{4}$ " I.P. at cor. see Run #140

~~C.S. File 54/16 Haines Field Book, page 415~~

also find B.T.s 25 follows -

Orig. 24" Now 48" D. FIR N. 85°W, 27 $\frac{1}{2}$ ft. (face)

Rebar scribed, "363 $\frac{1}{4}$ 527 BT" 2/10e.

Orig. 40" FIR S. 45°E, 2° ft.

Now Burned & Badly decayed Remnants of
stump only - no scribe fd.

Haines B.T. - 12" Now 14" I, cedar S. 69°E, 23 $\frac{5}{8}$ ft.

scribed, " $\frac{1}{4}$ 526 BT" E Haines Button on face.

CRACKED FROM ground up - beginning to rot.

We do not set BRASS cap. - MK. New B.T.s -

10" I, cedar, N. 54°W, 40 $\frac{1}{4}$ ft.

Mkd. " $\frac{1}{4}$ 527 CS BT"

24" I, cedar S. 49°E, 26 $\frac{5}{8}$ ft.

Mkd. " $\frac{1}{4}$ 526 CS BT"

This cor. Lies on S. Slope of
SPUR course S.W.

Sept 26, 1966

U.R.T.
J.H.

(Signature)

*145

C.S. File No. 54/16-24