

35/54

Renew Sec. Cor. 58/59 T235 R5W

Fd. unrecorded & unmarked stone
at cor. point by old oak fence
cor. post - fences mostly gone,
& o.B.T. as follows -

orig. 12, "Now 48" W, oak. N, 89° W, 636² ft
alive - previously opened - Rotted out
we open higher - & find "W 55" Reverse
scribe - No Trace other o.B.T.s

probably Due to cultivation many
years back - at cor. point in
place of stone set 1 "I.P. & BRASS
cap MKd." COUNTY SURVEYOR'S
OFFICE 1969 T235 ^{55/54}/_{58/59}

R5W "Reset Rock alongside & MK.
New B.T.s -

20" B. oak S, 43° W, 277 ⁴/_{ft.}

Mkd. "T235 R5W 58 CS BT"

20" W, oak S, 84° E, 271 ³/_{ft.}

Mkd. "T235 R5W 59 CS BT"

No other Trees close.

This cor. lies in field.

O.K. D.
S.W.D.

Sept 26, 1969

VRT.
J.G.H.
K.R.P.

#84
O.B.T. Tracy

Theodore Petersen
C.S. No. 54/11a-55