

Renew SE DLC 45 | SW DLC 44 T235 R5

Fd. O.B.T. as follows -

ORIG. 20" Now 36" B. OAK N. 25° E 184'-⁵/₈

Now sawed stump - Badly Decayed

We open & find "1" 1" Reverse

scribe & Reverse of Axe Notche -

at Bearing & Dist. for NW. O.B.T.

we find shallow hole. at cor.

Point set 1" I.P. & Brass cap mkd.

"COUNTY SURVEYORS OFFICE"

1969 T235 R5W ^{SE}DLC 45 | ^{SW}DLC 44"

& MK New B.T.s -

7" D. FIR N. 56° E, 94 ft.

Mkd. "SW DLC 44 CS BT"

11" B. OAK N. 61° W, 387 ft.

Mkd. "SE DLC 45 CS BT"

fence cor, with fences N. & E.

Bears S. 71° W, 50 ft.

Oct 13, 1969

V.R.T.

J.G.H.

V.D.P.

V.R.T. Tracy