

Renew Sec. Cor. $\frac{514}{523} | \frac{513}{524}$ T235 R5W

Do not find 2" cor. pipe as called
for in Ren. #10 - Find Ren. B.T.s as foll^{ows}

15" now 16" W. oak S. 72 1/2° W. 21' ft

2 live - healed blaze -

20" now 21" B. oak S. 32 1/2° W. 48 5/8 ft.

2 live - healed blaze - NE & NW. Fir
B.T.s now 5 stumps - scribe marks visible -

2" cor. point set 1" I.P. & BRASS cap

Mkd. "COUNTY SURVEYORS OFFICE

1969 T235 $\frac{514}{523} | \frac{513}{524}$ R5W" & M.K. new

B.T.s -

16" B. oak N. 1° W. 82° ft.

Mkd. "T235 R5W 514 CS BT"

24" W. Fir N. 66° E. 13 5/8 ft

Mkd. "T235 R5W 513 CS BT"

OBT. to S.W. now low cut

stump. - This cor. lies in
Log Road - course N. (Note - set
BRASS cap 8" below surface)

Oct 2, 1969

V.R.T.
J.G.H.
V.D.P.

V.R.T. Ray

0' 5" W. 13°

#88

C.S. File No. 54/16-61