

Renew Sec. CoR. ^{511 512} 514 513 T255 R3W

Fd. G.L.O. BRASS Cap MKd. "T255 R3W

^{511 512}
^{514 513} 1943 " & steel fence Post alongside.

& BTs as follows -

ORIG. 36 "Now 40" FIR N, $86\frac{1}{2}^{\circ}$ E, 26 $\frac{4}{4}$ FT,

Shows visible BARK scribe "512" - 2 live,

ORIG. 20 "Now 23" R. cedar S, $68\frac{1}{4}^{\circ}$ E, 15 $\frac{2}{2}$ FT,

Badly BURNED, - 2 live - face BURNED,

ORIG. 24 "Now 30" Hemlock S, 53° W, 11 $\frac{9}{9}$ FT,

previously opened - scribe visible, 2 live,

N.W. orig. B.T. now STump, 1943 Resurvey

B.T. to N.E. down & Rotted. we MK. new BTs -

30" Hemlock S, 53° W. 11 $\frac{9}{9}$ FT

Rescribed " T255 R3W 514 CS BT "

6" D. FIR N, 53° W. 20 $\frac{E}{E}$ FT.

Mkd. " T255 R3W 511 CS BT "

17" R. cedar S, 41° E, 49 $\frac{1}{1}$ FT,

Mkd. " T255 R3W 513 CS BT "

10" Hemlock N, 16° E, 15 $\frac{5}{5}$ FT

Mkd. " T255 R3W 512 CS BT "

CoR. Lies on VERY steep N.W.

Slope.

July 28, 1966

V.R.T.

J.B.

J.H.

~~W.R. & R. [unclear]~~
* 492
O.K. O.W.B.

54/27-53