

Review $\frac{1}{4}$ $\frac{512}{513}$ T255 R2W

Fd. 1962 cadastre 21 BRASS cap on
2 1/2" I.P. pushed out of position &
Buried 6" below surface of ground.

We Reset Cad. BRASS cap in proper
position from following B.T.'s -

1962 13" now 14" Hemlock South 28 1/2 ft.
alive - badly injured & filled to 3" of
top of unhealed, scribed block.

Orig. F.R. B.T. S. 54° W, 12 1/2 ft.

Now only shattered remains of
sawed stump - no scribe sd.

No Trace B.T. to N.E. - MK. New B.T.'s

8" Hemlock N. 19° E, 14 1/2 ft.

Mkd. " 1/4 512 CS BT "

24" cedar S. 57° W, 51° ft.

Mkd. " 1/4 513 CS BT "

also set 6 ft. Red steel fence post

along side BRASS cap. This cor.

Lies in recent logged off unit

approx 200 ft. N. of East fork of

Rock Creek Road.

March 17, 1967

J.P.T.

J.P.T.

P.W.

C.S. File No. 54/27-118
O.K. S.W.B.