

Renew  $\frac{1}{4}$  <sup>R3W</sup> 524 | 519 R2W T245

Fd.  $\frac{1}{2}$ " I.P. set at cor. point &

"W" Method B.T. - unrecorded - O.B.T.s 25 follows

orig. 12" now 14" Hemlock S. 35° E. 15 8 ft.

Now down & out of position - we find probable stump hole - face rotted no scribe.

orig. 12" now 14" Hemlock S. 88° W. 17 2 ft.

Now stump - leaning - "BT" scribe visible on previously opened blaze.

"W" B.T. - 30" D. Fir stump S. 48° W. 15 0 ft.

"W" Nail & Tag - we set " $\frac{1}{4}$  524 CS BT"

set 1" I.P. & Brass cap in place of I.P.

Mkd. "COUNTY SURVEYOR'S OFFICE

1968 T245 R3W  $\frac{1}{4}$  524 | 519 R2W" &

Mk. New B.T. -

20" cedar stump S. 28° E. 40 1 ft.

Mkd. " $\frac{1}{4}$  519 CS BT"

This cor. lies on moderate N.W.

slope changing to very steep

N.W. slope. Reset I.P. alongside

Brass cap.

March 6, 1968

J. R. Tracy

JRT  
J.H.  
J.P.

#42-124-2

070-124-3

O.K. J.W.B.

C. S. File No.

524-145