

Renew  $\frac{1}{4}$  cor. RIW 525 + 530 RIE T245

Fd. 1965 C.S. BRASS cap out of  
ground - old cor. stone in place &  
BITS as follows - (see-Rev # 46)

orig. 10" now 18" FIR S. 28  $\frac{1}{2}$ ° E. 25  $\frac{1}{2}$  ft. (face)  
alive "4" scribe visible on blaze we  
opened in 1965 -

orig. 30" now 37" FIR N. 49° W. 38  $\frac{3}{4}$  ft. (face)  
Shows good scar - alive - broken off  
about 60 ft. high.

our 1965 9" Yew S. 21° E. 19  $\frac{1}{2}$  ft

alive - scribe ok - blaze split -

Reset 1" I.P. & BRASS cap at cor  
Reset old cor. stone along side  
MK. New BITS -

18" cedar S. 18° W. 20  $\frac{1}{4}$  ft.

Mkd. "  $\frac{1}{4}$  S 25 DCS BT "

16" cedar S. 44° E. 33  $\frac{2}{3}$  ft

Mkd. "  $\frac{1}{4}$  S 30 DCS BT

This cor. lies on N-S cutting  
line - unit in sec 25 & approx.

400 ft. N. of Chilcoot Creek  
Road #

#89  
May 12, 1970

U.R.T.  
V.R.P.

O.H.  
T.W.A.

V.R. Tracy  
C.S. No. 54/27-206