

Review $\frac{1}{4}$ COR. 521/522 T245 R2W

Fd. Mound of stones - apparent
COR. Stone Broken - No MKs, Fd,
O.B.T.s as follows -

orig. 12" Now 18" Cedar N, $22\frac{1}{2}^{\circ}$ E, 7⁹ ft.
2 live - Now healed Blaze - we Rescribe
" $\frac{1}{4}$ 522 CS BT "

orig. 18" Now 24" Fir N, 25° W, 19⁸ ft.
2 live - Shows good scars - we
Rescribe " $\frac{1}{4}$ 521 CS BT "

2⁺ COR. point set BRASS cap
12" inground & Build mound of
stone around pipe & MK BRASS
" COUNTY SURVEYORS OFFICE
1969 T245 $\frac{1}{4}$ 521/522 R2W "

& MK new B.T. -

7" Yew S, 81° W, 27³ ft.

Mkd. " $\frac{1}{4}$ 521 CS BT "

Weyerhaeuser Reference - 236"

Fir Stump S. 78° E, 3⁰ ft. To

"W" Nail - This COR. lies on

Very steep S. Slope APPROX

420 ft. North of creek course S.E.

August 20, 1969

K.R.T.

J.G.H.

U.S. FILE NO. P.

54/127

*66 of R.T. Tracy

W.S.
251