

Renewal

523524  
526525

T315 R2W

Found

30" Pipe Now stump N67W 49<sup>±</sup>  
Scribe visible "T315 R2W S23 BT"

36" Pipe Now stump S32W 77<sup>±</sup>  
Scribe visible "N2 24"

15" Laurel Now 22" S45E 23<sup>±</sup>  
Faint Scribe visible on old Battery  
Face

6" Laurel Now 15" N88E 32<sup>±</sup>  
Face Rotation

Revisited

Sat Brass cap at Sec cor 14th  
county surveyors office

T315 R2W

523524  
526525

1966

DIETZEN NO. 385-6

New Bearing Trees

10" D. Fir S62E 41<sup>±</sup>  
Scribed T315 R2W S25 CS BT

14" Laurel N76E 29<sup>±</sup>  
Scribed T315 R2W S29 CS BT

6" D. Fir N33W 13<sup>±</sup>  
Scribed T315 R2W S23 CS BT

10" D. Fir S76W 34<sup>±</sup>  
Scribed T315 R2W S26 CS BT

Notes:

This cor line in East + South  
Fence cor.

\*59  
OK. J.W.P.

North

6-28-20  
C.S. No. 1110  
T.C.