

Renewal SW cor sec 31 only T31S R2W

Found:

1" Iron P.P. at cor.

OBT 36" D Fir NW 90° N 13E 23°

8" Hemlock S 74E 20°

Tree dead
Scribe visible "S1" "T32S"

16" D. Fir S 6 1/2 E 15°
Tree now snag Bark removed

19" W. Fir NW 15° N 49E 45°

Scribe visible

Iron P.P. in good shape

As noted Rd. Bears East

75°. However it lies in an alk
unit & grows over with small
alder.

Best way to reach corner is
by walking down same, from
Main Rd.

New Bearing Tree

27" D. Fir S 32 1/2 E 34°

Scribed T32S R2W S1 S3 BT

Renewal #20, T31-2

8-29-66

#50
#16-T32-2
#191-T32S

[Signature]

X #120
O.K. J.W.B.

C.S. *[Signature]* 5/28 118

DIETZGEN NO. 385-6