

Renewal

529 | 528
532 | 533

7315 R6W

Found:

4" W. Fir Now 6" S77 $\frac{1}{2}$ E 74 $\frac{1}{2}$
Scribe Marks visible

4" D. Fir Now 7" N38E 36 $\frac{1}{2}$
Shows good scar

4" D. Fir Now 6" N4W 76 $\frac{1}{2}$
Scribe Marks visible

6" Fir S 92 $\frac{1}{2}$ W 66 $\frac{1}{2}$
Blow down.

$\frac{1}{2}$ " Iron Pipe Torn out of ground.

Renewed:

Set Brass cap at sec cor MKQ,
County Surveyors Office

7315 R6W

529 | 528
532 | 533

1966

New Bearing Tree

40" D. Fir N84W 98 $\frac{1}{2}$
Scribed 7315 R6W S29CS BT

This cor lies on south edge
of Rd Squared State of Brass
cap

10-7-66
~~7/2/67~~
~~7/2/67~~
C. S. H.

Renewal #18

107 B. K. J. W. B.

C. S. File No. 54/31-2