

Renewal
Found orig. 573

7/13
9/10

T313 R9W

10" cedar now 12" N42E 21 1/2
Scribe visible "53" "731" "R9W"
I find Bearing to be N21E

30" cedar now 120W N49W 37 1/2
I find this Bearing to be N39W

24" P. Fir now stub S41W 53
This tree has burnt face
I find this Bearing to be S30W

18" P. Fir now 22" S42E 53
Shows good scars
I find this bearing to be S72E

(Renewal #6)

Also 7/8" Hex Rod. I do not hit
any thing but I bearing from this
point.

Renewed:

By using intensification of all 4 Distances
I set Brass cap MSD,

County Surveyors office
T313 R9W

59/53
59/310

1967

Now Bearing Trees:

12" Hemlock S84 W 149 1/2
Scribed T313 R9W S9 CS BT

6" W. Fir N41 W 133 1/2
Scribed T313 R9W S7 CS BT

7/8" Hex Rod is 20 N10 W

2-20-67

[Signature]
C.A.B.

* #53

C.S. File No. 54-32-3

DIETZEN NO. 385-6