

Renewal

37  
3

T31

T32S

RBW

Found:

14" D. Fir now 50" S2E 39 $\frac{1}{2}$

Fast "82" visible

Photo notes Below Main Face

No trace of 7" Fir now 19 $\frac{1}{2}$

Also

I. P. K. at  $\frac{1}{4}$  cor. (unrecorded)

Tree with face but no scribing at N10E 15 $\frac{1}{2}$

Renewed:

Along Side I. P. K.

Set Brass cap at  $\frac{1}{4}$  cor. AND,

County Surveyors office

T31S RBW

$\frac{1}{4}$   $\frac{539}{53}$

T32S

1967

New Bearing Tree

10" D. Fir S37E 18 $\frac{1}{2}$   
Scribed  $\frac{1}{4}$  53 CS BT

10" D. Fir N10E 16 $\frac{1}{2}$   
Scribed  $\frac{1}{4}$  539 CS BT

Note:

As in orig notes spring branch  
2 chains (132 $\frac{1}{2}$ ) East of  $\frac{1}{4}$  cor

1-11-66  
~~CPB~~  
CPB

#31-132-8

\*O.K. J.V.B.  
#33-T31

C.S. File No. 54/36-74

DIETZGEN NO. 385-6