

Review  $\frac{1}{4}$   $\frac{523}{526}$  T265 R2W

Fd. 1916 G.L.O. BRASS CAP MKd " $\frac{1}{4}$   $\frac{523}{526}$ "

& Shattered Stump of O.B.T. as follows

24" cedar S. 25° E, 3 $\frac{3}{4}$  ft.

No scribe fd. - No Trace N.E. B.T.

Both B.T.'s were probably destroyed

by Logging several years ago. we MK.

New B.T.s -

28" cedar N. 23° W, 60 $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  523 CS BT"

39" cedar S. 85° E, 116 $\frac{6}{8}$  ft.

Mkd. " $\frac{1}{4}$  526 CS BT"

This cor. lies on N.W. slope  
in N.E. cor. of cutoff unit.

August 4, 1967

U.R.T.  
J.H.  
D.W.

*(Signature)*

#74

G.W. J.W. B.

G.S. File No. 54/40-99