

525/525

Renew Sec. Cor. 335/336 T275 R2W

Fd U.S. Plywood Alum. CAP properly
MKd. at cor. point & B.T.S as follows
Sec Ren. # 36

26" Fir STump S. 49° W. 5 6/8 ft,
good orig. scribe visible. (O.B.T.)

36" Fir STump N. 55° W 20° ft,
Rescribed "526 BT" (O.B.T.)

18" Yew S. 65 1/2° E. 26 2/3 ft.

2 live - Rescribed "536 BT" (O.B.T.)

22" Fir STump N. 15 1/2° E. 12 1/2 ft,
scribed "525 BT" (SHRUMS now BT)
we MK. new BT-

15" Hemlock S. 62° W. 32 2/3 ft,
MKd. " T275 R2W 535 CS BT "

No Live Trees available N. of cor.
also set 6 ft. Steel fence
post along side Alum. Cap,
This cor. lies N.E. slope
clearcut in sec. 5, 25, 26, & 35.

Oct. 15, 1968

WRT
J.H.

J. R. Tray

#75

D.K. J.V.V.B

G.S. File No. 54/40-80