

Review $\frac{1}{4}$ 59/510 T275 R2W

Fd, 1957 ccd. BRASS cap in place

& B.T.s as follows -

orig. 22" W. FIR S. $73\frac{3}{4}^{\circ}$ W, 14 \pm ft

Now snug, scribe visible. No trace

orig. madrone S.E. -

1957 BT, To S.E. Lying face down &
in falling hit 1957 NW. BT, leaving
only a 6 ft high stub showing scribe,
we MK new B.T.s -

16" cedar N. 78° W, 17 \pm ft,

Mkd. " $\frac{1}{4}$ 5 9 CS BT"

10" Hemlock N. 38° E, 42 \pm ft,

Mkd. " $\frac{1}{4}$ 5 10 CS BT"

This cor. lies on N-S cutting
line - cutoff in Sec 10.

Dec. 10, 1968

U.R.T.
F.W.J.
V.P.

~~9/PT Tracy~~

O.K.

J.W.B.

O#123

U.S. File No.

57/40-149