

Renew  $\frac{1}{4}$  532/533 T275 R2W

Fd. C.B.T.'s as follows - (1911 Resurvey)

36" Now 40" FIR N.  $53\frac{2}{3}^{\circ}$  E. 23  $\frac{1}{2}$  ft.

Now sawed stump - we open & find

" $\frac{1}{4}$  533" scribe & Reverse.

36" Now 40" FIR N.  $30^{\circ}$  W. 5  $\frac{3}{4}$  ft.

Now sawed stump - previously opened

& shows " $\frac{1}{4}$  532" scribe, 2<sup>d</sup> COR.

point set 1" I.P. & Brass cap

Mkd. "COUNTY SURVEYOR'S OFFICE

1968 T275  $\frac{1}{4}$  533/532 R2W" & set

6 ft. steel fence post along side.

BRASS cap - MARK new B.T.s

10" Hemlock N.  $80^{\circ}$  E. 14  $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  533 CS BT"

12" Hemlock S.  $45\frac{1}{2}^{\circ}$  E. 23  $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  533 CS BT" (No trees

available west of line in Sec. 32)

The  $\frac{1}{4}$  COR. recorded in Ren #23

Bears S.  $63^{\circ}$  E. 20  $\frac{3}{4}$  ft. - 2

$1\frac{1}{2}$ " I.P. with 1" steel pipe &  $2\frac{1}{2}$ "

Alum. U.S. plywood cap with B.T.

apparently set from wrong

Bearing & Dist. FROM C.B.T. TO N.W.

Dec. 13, 1968

#125 W. R. Tracy

W.R.T. O.K.

F.W.T.

C.S. File No. 154/40-155