

Review  $\frac{1}{4}$  <sup>514</sup> 523 T275 R2w

Fd. U.S. Plywood Alum. Corp. properly  
MKd. & OB.T. as follows - See

Ren. #37

15" Now 24" FIR S. 34° E, 17<sup>8</sup> ft,

2 live - shows good SCAR - we Rescribe  
"1/4 523 CS BT"

15" Now 24" FIR N. 20° W, 4<sup>5</sup> ft,

open & shows scribe MKs.

we MARK. New BT. -

18" D. FIR N. 76° W, 10<sup>4</sup> ft,

Mkd. "1/4 514 CS BT"

This cor. Lies very gentle  
N.E. slope in old growth  
Timber.

Dec. 23, 1968

U.R.T.  
F.W.T.  
V.P.

G.R. Tracy

O.H.  
J.W.B.

#129

C.S. File No. 59/40-161