

Renewal

S157 S/A
522 / 523

T30S R3W

Found
O.B.T.30" Fir snag
Face burnt

SIDE

19E

38" Fir snag
Face burnt

N45W

19E

Renewal 923

19" D Fir now 16"
"BT" visible

S24W

56E

3" D Fir now burnt
shows scar

S18W

15E

3" D Fir now burnt
shows scar

S58W

7E

2" D. Fir now burnt
shows scar + parts of scabbing

N74E

6E

1" Iron Pipe at Sec cor.

New Bearing Trails

10" D. Fir

S10W

80³

Scribed T30S R3W 522 CS BT

19" D. Fir

S52W

79³

Scribed T30S R3W 522 CS BT

Note

Can now follow in burn no other
trees within reason to scabbing.Also cor lies on steep west
slope approx 70° north of small
ravine

9-19-67

J.M.P.
J.C.S.

199

O.K. J.W.12

C.S. File No.

92/52-6