

Renewal

8/9
17/16

T33S R6W

Found

O.B.T.

15" W. Oak Now Rotten Stump Tree Now
S43E 67° Reverse Scribe Found "S" "11/13"
9 other marks.

50" D. Fir Now Down Burnt S60W 72°
Scribe Found "O.B.T."

24" W. Oak Burnt out N35E 81° (Rec. N50E)
No Scribing

40" Fir Now Hole N15W 17°

It seems all Dist are sloped
By using 3 Bearings & 7 Slope Dist
I found as follows

Set Brass cap at Sec cor M&D,

County Surveyors Office
T33S R6W

8/9
17/16
1967

New Bearing Trees.

11" D. Fir N30E 16°
Scribed T33S R6W S 9 CS BT

15" D. Fir S3E 32°
Scribed T33S R6W S CS BT

19 D. Fir S23W 17°
Scribed T33S R6W S 17 CS BT

10" Laurel N60W 15°
Scribed T33S R6W S 8 CS BT

10-27-67
J.C.B.

Q35

O.K. J.W.B.

C.S. File No. 54/53-29

**FILED
RECEIVED**

OCT 24 1967

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**