

Fd. Sec. Cor. $\frac{53}{510} | \frac{52}{511}$ T305 RIW

Fd. 1967 U.S. Plywood Aluminum Corp
properly MKd. & O.B.T.s as follows -

12" Now 18" Maple S. 8° W. 25 2 ft.

2 live - Rotted out - No scribe -

48" Now 60" Fir N. 85° E. 34 $\frac{3}{4}$ ft.

No scar - or bark scribe - No

Trace Hawthorn's BT's S.E. or NW. - we

find other O.B.T.s unrecorded -

40" W. Fir S. 75 $\frac{1}{2}$ ° E. 83 $\frac{8}{16}$ ft.

2 live - previously opened & shows scribe.

72" D. Fir N. 36° W. 39 2 ft

2 live - shows good scar -

& drums New BT's as follows -

9" W. Fir S. 63° W. 14 $\frac{5}{16}$ ft.

Mkd. "510 BT"

9" W. Fir N. 66° W. 28 $\frac{5}{16}$ ft.

Mkd. "53 BT" - Note - we do not find

a branch 1" wide 6 $\frac{6}{16}$ ft. S. of cor. as called for.

9 NOV. 4, 1967

URTT
J.H.
U.P.

○ #18