

Renewal

S30
S31

T30S R1E

Found

18" D. Fir Blow Down S20E 86
opened 15' "E" 730" "3"

34" D. Fir Now 58" N44E 16"
This dist has to be slope dist
to match bearings w/ other dist

Brass cap pulled out of ground
by other blow down.

Renewal

Reset Brass cap at Sec. cor 14th,
General land office

T30S T30S
R1W S30
S31 R1E
1923

DIETZGEN NO. 385-6

New Bearing Tree

25" D. Fir S87E 30"
Scribed T30S R1E S31 CS 87

Note
This cor lies 236' North of 1/4 36
FILED T30S R1W - NE

RECEIVED

1-23-68

JAN 23 1968

[Handwritten signature]

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

44-730-1E

44-730-1W O.K. J.W.B.

C. S. File No. 54/59-46