

Renewal

3 only

T30S R1W  
T31S R1W

Found:

Brass cap at  $\frac{1}{4}$  cor down 1050

General lead office  
T30S R1W

$\frac{1}{4}$  S3  
T31S  
1925

30" D. Fir New snag S84W 239° (Rec 25.7)  
opened for scribe "3" BT

Renewal:

I Reset Brass cap at orig.  
Dist from  $\frac{1}{4}$  of ~~39~~ only 180.2  
in large mound of stone

No trees within reason in  
South Quad.

New Bearing Tree

18" D. Fir N59W 129°  
scribe  $\frac{1}{4}$  S3 CS BT

Mound of stone <sup>12x2</sup> South, 19° E of  
 $\frac{1}{4}$  cor.

Note This cor lies on East  
slope, in a large opening all rocks.

7-15-68

*[Handwritten signature]*

1450-T31-1

D. W. J. W. R.

119

9104

C. S. File No. 54/59

DIETZGEN NO. 3856-6